



INSPEC Technical Services (Kunshan) Co Ltd • 8 Jin Yang East Road • Lu Jia Zhen • Kunshan • Jiangsu • China Email: testing@inspec.asia Website: www.inspec-international.com

i: +86 (512) 5011 2646 Fax: +86 (512) 5011 2656

# **Test Report**

# CSA Z259.10-2012 (R2016) Full body harnesses

Report no: 2.19.03.42

Client: Jinhua Jech Tools Co., Ltd

No. 1448 Tongxi Road Bailongqiao Town Jinhua City 321025

Zhejiang China

Manufacturer: Jinhua Jech Tools Co., Ltd

Client order: T/0468

Date received: 25 January 2018

Model: JE115021

Dates of tests: 8 March 2018 to 16 April 2018, and 13 March

Signed: Issued: 15 March 2019

Steven Sum, Laboratory Manager Page 1 of 10

ECH

BESH

ECH

#### Conditions

This report may be reproduced and distributed to your clients, provided that it is reproduced and distributed in full.

Specimens will be disposed of four weeks from the date of this report, unless otherwise instructed.

Opinions, comments and interpretations expressed in this report are shown in italics.

Copies of INSPEC interpretations referenced in this report are available upon request.

Tests marked 

are not included in our ANAB Scope of Accreditation.

BESH

This report has been provided in accordance with our standard Terms of Business, which can be viewed at, and printed from:

http://inspec-international.com/ToB.pdf

ESH

BECH

If you have difficulty accessing the Terms of Business, you may contact us for a copy.

# Summary of assessment\*

Clause	Requirement	Assessment (See Key)
4.1	Fibre webbing ®	Ltd
4.2	Connecting components	Pass
4.3	Keeper	Pass
4.4	Tongue type buckles	NAp
4.5	Fall arrest indicator	Pass
4.6	Avoidance of the genital area	Pass
4.7	Classification	Pass
4.8	Class A – Fall arrest	Pass
4.9	Class D – Suspension and controlled descent	17 m =
4.10	Class E – Limited access	
4.11	Class L – Ladder climbing	
4.12	Class P – Work positioning	Section Section
4.13	Alternative applications	
4.14	Alternative materials & construction	
5.2.1	Drop test - class A, feet first	Pass
5.2.2	Drop test - class A, head first	Pass
5.2.3	Drop test – class P	
5.3	Fall arrest indicator static test	
5.3	Fall arrest indicator dynamic test	Pass
7.1	Markings	Ltd
7.2	Information	Ltd

# INSPEC Interpretation applies

#### Kev

3	Shading shows the clauses requested. Any other clauses were not requested.
Pass	Requirement satisfied.
Ltd	Testing requested was insufficient completely to verify compliance with the clause. Refer to the "Result details" section for more information.
Fail	Requirement not satisfied. Refer to the "Result details" section for more information.
NAs	Assessment not carried out.
NAp	Requirement not applicable.
NT	Requested but not tested due to early termination following failure.

Assessment relates only to those specimens which were tested and are the subject of this report.

ECH

#### Submission details

Product	Quantity	Date received	INSPEC specimen no.
Full body harness, model JE115021	03		2F03101 to 2F03103
Webbing, yellow colour, part number JEW-1B2Y	10 m	5 February 2018	2F03001A to 2F03001E
Webbing, black colour, part number JEW-2BLACK	10 m	Sh	2F03002A to 2F03002E

#### **Procedures**

The specimens detailed within the submissions above were used for the tests covered by this report.

Testing was performed in accordance with CSA Z259.10-2012 (R2016) unless otherwise specified below. Reference should be made to the standard when reading this report.

Unless stated otherwise, specimens were tested in the condition as received by INSPEC.

Testing was performed at INSPEC's laboratory in Kunshan, China.

DECH

ESH

ECH

The full body harness was first tested and reported in Inspec Test Report 2.18.04.13

This report was issued to include the assessments of the Markings and Information material.



ESH:

### Result details

#### 4.1.1 Fibre webbing

Not assessed. Manufacturer to certify.

NAs

#### Stitching and cut ends

Specimen 2F03101 was assessed.

a) All machine stitching was not assessed. Manufacturer to certify.

NAs

 b) The ends of all threads were not assessed. Manufacturer to certify. c) The cut finishes of all webbings were hot cut to prevent fraving.

NAs Pass

#### 4.1.3 Width and strength

Specimen 2F03101 was assessed.

The minimum width of straps were as follows:

Shoulder straps

45 mm

Thigh straps

45 mm

Sub-pelvic straps

45 mm

These were not less than the minimum 41 mm specified.

Pass

When tested as specified with the 22.0 kN load, the straps 2F03001A to 2F03001E and 2F03002A to 2F03002E performed as follows:

Shoulder straps withstood the test without breaking withstood the test without breaking Pass Pass

Thigh straps Pelvic straps withstood the test without breaking

Pass

#### 4.2 Connecting components

BECK

#### 4.2.1 Full body harness component connections and terminations

Specimen 2F03101 was assessed.

Connection of all full body harness components to each other and terminations of all full body harness components were by means of Class I or Class II connectors.

Pass

A dorsal D-ring was used to connect to fall protection system.

Buckles were used for connecting straps together.

#### 4.2.2 Connection to systems or elements external to the full body harness

4.2.2.1 There were no external systems or non-integral elements.

NAp

4.2.2.2 The full body harness was not integrally connected to a fall arrest systems or elements.

BECH

NAp

#### 4.3 Keeper

Specimen 2F03101 was assessed.

All webbing straps that end with a free end had a keeper loop of the required size to reduce the possibility of accidental disengagement of the strap from its functioning position. Pass

#### 4.4 Tongue type buckles

Specimen 2F03101 was assessed.

Tongue buckles were not incorporated in the full body harness.

NAp

#### 4.5 Fall arrest indicators

Specimen 2F03103 was assessed.

The full body harness included a built-in fall arrest indicator.

Pass

When tested as required by 5.3 and as specified in 6.2.6, the fall arrest indicator activated to give a permanent, readily visible warning.

Pass

#### 4.6 Avoidance of the genital area

Specimen 2F03101 was assessed.

Load bearing components of the full body harness, when worn correctly and properly adjusted did not pass over the genitals of the test subject.

Pass

#### 4.7 Classification

All specimens were assessed.

They satisfied the requirements of a Class A full body harness.

Pass

The full body harness was classified as follows:

Class A: Fall arrest

Pass

#### 4.8 Class A, Fall arrest

Specimen 2F03101 was assessed.

 a) One Class 1 dorsal connector (part number JE516041) was affixed to both shoulder straps. Pass

 The full body harness was not integrally attached to a certified subsystem or element with a dorsal Class I / Class II connector affixed directly to both shoulder straps. NAp

A sub-pelvic strap was fitted.

The dorsal connector was a sliding D-ring.

A back strap was sewn across both shoulder straps at the dorsal area to limit the downward creep of the D-ring towards the waist. Pass

#### 5.2 Drop test

#### 5.2.1 Class A. Feet first

Specimen 2F03101 was assessed.

a) The test mass was arrested.	Pass
<ul> <li>b) The test mass remained suspended for 10 minutes after the drop.</li> </ul>	Pass
c) All connectors remained connected.	Pass
d) The angle of the test mass at rest after the drop was 12°. This is less than the maximum 30° permitted.	Pass
e) The fall arrest indicator activated to give a permanent, readily visible warning.	Pass
f) The harness stretch "xh" was 9.13 inches. This is not more than the value "18 inches" stated in the manufacturer's instructions.	Pass

#### 5.2.2 Class A, Head first

Specimen 2F03102 was assessed.

The test mass was arrested,	Pass
<ul> <li>The test mass remained suspended for 10 minutes after the drop.</li> </ul>	Pass
c) All connectors remained connected.	Pass
<ul> <li>d) The fall arrest indicator activated to give a permanent, readily visible warning.</li> </ul>	Pass

## 5.3 Fall arrest indicator - Dynamic test

Specimen 2F03103 was assessed.

a)	The fall arrest indicator activated.	Pass	
61	There was a decreased readily visible warries after the fact	Dage	
D)	There was a permanent readily visible warning after the test.	Pass	

## 7.1 Marking

The markings shall appear in both English and French on a durable label intended to last the life of the product and shall be affixed to the full body harness was not assessed.

Labels supplied electronically were used for assessments. The markings on the labels appeared in both English and French.

The following items were shown:

a)	The identification of the manufacturer/vendor was given. "JECH"	Pass
b)	The model number was given. "JE115021"	Pass
	The designation CSA Z259.10 was given	Pass
d)	The applicable class was marked in words in accordance with the titles of clauses 4.8 to 4.12.	Pass
	Applicable pictograms as per Figs 1 to 5 were given	Pass
	The minimum height of the pictogram was not assessed	NAs
	The word "size and grandeur" were given	Pass
e)	Date of manufacture (by year and month) was given. "201804"	Pass
	Space for personal identification was provided. "Name"	Pass
19/15		W//
The second		

#### 7.2 Information material

BECH

Information written in both English and French shall be provided with each full body harness offered for sale was not assessed.

NAs

Information material supplied electronically in English and French were used for assessment.

The following items were shown:

b 1		100 000
a)	The intended purpose of the device was given.	Pass
b)	A hazard warning was given.	Pass
c)	Instructions on proper method & limitations of use were given.	Pass
d)	The expected stretch of the harness when arresting a fall, "xh = 18 inches" was given.	Pass
	An instruction that this distance be taken into account, re: calculating clearance below a worker was given.	Pass
e)	Fitting and adjusting instructions were given.	Pass
	Applicable pictograms as per Figs 1 to 5 were given	Pass
f)	Recommendations for care (cleaning, maintenance and storage) and inspection (including frequency) were given.	Pass
g)	The purpose and function of the fall arrest indicator were given.	Pass
h)	The required warning was given.	Pass
i)	Application, use and connection of evacuation device to the harness was given.	Pass
j)	Manufacturer's name, address and telephone number were given.	Pass



ECH

ECI:

#### Estimates of the uncertainty of measurement

Clause	Test	Uncertainty
4.1	Fibre webbing – strap width	0.2mm
4.1	Fibre webbing – strap loading	See Note 1
4.2	Connecting components	See Note 1
4.3	Keeper	See Note 1
4.4	Tongue type buckles	See Note 1
4.5	Fall arrest indicator	See Note 1
4.6	Protection of the genital area	See Note 1
4.7	Classification	See Note 1
4.8	Class A – Fall arrest	See Note 1
4.9	Class D – Suspension and controlled descent	See Note 1
4.10	Class E – Limited access	See Note 1
4.11	Class L – Ladder climbing	See Note 1
4,12	Class P – Work positioning	See Note 1
4.13	Alternative applications	NAs
4.14	Alternative materials & construction	NAs
5.2	Drop test – angle at rest	±0.2°
5.2	Drop test – stretch	±1.4%
5.3	Fall arrest indicator static test	See Note 1
5.3	Fall arrest indicator dynamic test	See Note 1
7.1	Markings	NAp
7.2	Information	NAp

- Note 1. The acceptance criterion for this test is a straightforward "Pass/Fail", rather than a numerical value. Consequently, as there is no value to be reported, uncertainty has not been reported either.
- Note 2. The uncertainty value is based on a standard uncertainty multiplied by a coverage factor k = 2, which provides for a confidence level of approximately 95%. Values expressed as a percentage (%) are relative.
- Note 3. It should be noted that the above values have not been taken into account when making assessments against the pass/fail criteria.





ECH

SH

BECH

# ANNEX

This Annex comprises one section.

Photograph of the product tested.

ECH

ECH

ECH

ECH

(1 page)

BECH

ECH

BECH

END OF REPORT

# Jinhua Jech Tools Co., Ltd – Full body harness, model JE115021

